



THE

Handweaving
Academy

Treadling Standard Overshot

Standard Overshot / OVERSHOT DEPARTURES

Treadling/lift plan instructions for each block:

For looms with tie-ups, [use Tie-Up #1](#).

To treadle Block A:

1. Throw the pattern shuttle through the Block A twill shed (Shafts 1&2 down, Shafts 3&4 up = twill treadle #1)
2. Throw the tabby shuttle through whichever plain weave shed was NOT used last.

To treadle Block B:

1. Throw the pattern shuttle through the Block B twill shed (Shafts 2&3 down, Shafts 1&4 up = twill treadle #2)
2. Throw the tabby shuttle through whichever plain weave shed was NOT used last.

To treadle Block C:

1. Throw the pattern shuttle through the Block C twill shed (Shafts 3&4 down, Shafts 1&2 up = twill treadle #3)
2. Throw the tabby shuttle through whichever plain weave shed was NOT used last.

To treadle Block D:


1. Throw the pattern shuttle through the Block D twill shed (Shafts 1&4 down, Shafts 2&3 up = twill treadle #4)
2. Throw the tabby shuttle through whichever plain weave shed was NOT used last.




Treadling and lift plan diagrams

For looms with tie-ups, [use Tie-Up #1](#).

Block order =
A x2, B x2, C x2, D x2




Standard overshoot
treadling, with tabby



Blue = pattern
White = tabby

Standard overshoot
lift plan, with tabby



Blue = pattern
White = tabby

Note that tabby is shown in the above diagrams.